



SAFETY UNLIMITED, INC.

Safety Tip of the Week

Hazards of Hot Work

Welding is a routine job on many worksites. However, this common task has hazards that can result in serious injury and property damage. Bystanders, as well as workers involved directly with welding, can be affected.

Experts estimate that 6% of all fires on industrial properties are caused by welding or cutting. The main cause is the sparks or hot slag welding necessarily produces.



Questions to Consider Before Beginning Hot Work:

- Does everyone understand the scope of the work?
- Have all the affected employees been notified?
- Have security and emergency response personnel been notified?
- Has the permit been filled out?
- Has the area been inspected before hot work is to start?
- Are all flammables/combustibles removed from the area?
- Has the area been evaluated to ensure that no flammable vapors are present?
- Is a fire extinguisher available?
- Are immovable fire hazards covered with a tarp or other non-combustible covering?
- Is hot work immediately stopped if conditions change, odors become present, etc., until the area is re-inspected?

You can protect yourself from the physical hazards of welding. Follow company policies for using PPE to prevent injury and follow them consistently. Correct any situations that pose a fire or electrical shock hazard.

If you have a safety concern about welding hazards, don't let it become an accident - report it to your supervisor.

DON'T GET BURNED...PRACTICE WELDING SAFETY!!